

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

May 14, 2007

Supervisor A

Mine Name:	Isla	nd Rocl	c#1
Operator Na	me:	John B	leazard

Permit number: S/045/066

Inspection Date: October 24, 2006

Time: 8:30 am

Inspector(s): Lynn Kunzler, DOGM

Other Participants: none Mine Status: Active

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2.	Public Safety (shafts, adits, trash, signs, highwalls)	$\overline{\boxtimes}$		
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation	\boxtimes	\boxtimes	
7.	Backfilling/Grading (trenches, pits, roads, highwalls,			
8.	Soils			
9.	Revegetation			

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

This site was originally inspected in July of 2005, and the operator was found to be operating without a permit. Subsequently, a SMO NOI was submitted on July 18, 2005 and a cash bond for \$2,500 was submitted.

During this inspection it was noted that much of the previous disturbance has been adequately regraded. It is assumed that these areas were also seeded since much of the vegetation observed would be considered desirable (vs. the cheatgrass that dominates the surrounding areas).

The area was free of trash and deleterious materials. There were no non-compliance issues noted.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The area is in compliance at this time.

Continue to monitor this site when in the area.

Inspector's Signature

K:pb

O:\M045-Tooele\S0450066-IslandRock\inspections\Insp-10242006 doc